

Bayou DeView Watershed Monitoring 16-800


Jennifer L. Bouldin, PhD
Ecotoxicology Research Facility
Arkansas State University



Cache River Watershed



Mid Bayou DeView River


- Weekly sampling



79.8% cropland
10.7% forest


Decrease in cropland
since 1999






Town of Waldenburg


Town of Waldenburg




Town of Waldenburg




Town of Waldenburg






Flag Slough Ditch


Flag Slough Ditch




Flag Slough Ditch




Flag Slough Ditch




Three Mile Creek




Three Mile Creek




Three Mile Creek




Three Mile Creek




Town of Pittenger




Town of Pittenger




Town of Pittenger




Town of Pittenger




Cow Lake Ditch




Cow Lake Ditch




Cow Lake Ditch




Cow Lake Ditch




May Branch Lateral




May Branch Lateral




May Branch Lateral




May Branch Lateral




Old Channel Bayou DeView



Old Channel Bayou DeView



Old Channel Bayou DeView



Old Channel Bayou DeView

